

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Fig. 1

CC-0701




Fig. 2








Fig. 3








Fig. 8

CC-0

Tygon tube strain relief




Fig. 9

CC-0






Fig. 10

Condenser Cooling Water Flow Rate



CC-0

Fig. 11







FIG. 13

K- ω plot showing Convective Ridge



Wave Number

FIG. 14




Fig. 15




FIG. 16

K- ω plot showing Acoustic Ridges
(in water with entrained air)




Fig. 17




FIG. 18

CC-0701

410




Fig. 19




Fig. 20




Fig. 21




Fig. 23

Hose clamped PCB208c01 load cell coherence with ported pressure sensor




Fig. 24




Fig. 25




Fig. 26




Fig. 27




Fig. 28




Fig. 29




Fig. 30